
HEG efficiency measurements
0th order
1st order
2nd order
3rd order
4th order
5th order
Efficiency
1
0.1
0.01
10^{-3}
2
5
10
20
50
Wavelength (Å)